

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	9202	electromagnetic ADJ clutch	USPAT; US-PGP UB; EPO; JPO	2003/07/09 08:39			0
2	BRS	L2	29	1 and zoom	USPAT; US-PGP UB; EPO; JPO	2003/07/09 08:59			0
3	BRS	L3	28	1 and 359/\$.ccls.	USPAT; US-PGP UB; EPO; JPO	2003/07/09 08:59			0
4	BRS	L4	19	3 not 2	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:10			0
5	BRS	L5	556	1 and lens	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:11			0
6	BRS	L6	48	2 or 3	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:11			0
7	BRS	L7	522	5 not 6	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:32			0
8	BRS	L8	280	7 and slid\$	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:40			0
9	BRS	L9	0	7 and slidability	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:40			0
10	BRS	L10	16	7 and lubricant	USPAT; US-PGP UB; EPO; JPO	2003/07/09 09:58			0
11	BRS	L11	321	359/696.ccls.	USPAT; US-PGP UB; EPO; JPO	2003/07/09 10:04			0
12	BRS	L12	40	11 and clutch	USPAT; US-PGP UB; EPO; JPO	2003/07/09 10:39			0
13	BRS	L13	2243	359/823.ccls. or 359/824.ccls. or 359/827.ccls.	USPAT; US-PGP UB; EPO; JPO	2003/07/09 10:40			0
14	BRS	L14	63	13 and clutch	USPAT; US-PGP UB; EPO; JPO	2003/07/09 10:40			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
15	BRS	L15	47	14 not 12	USPAT; US-PGP UB; EPO; JPO	2003/07/09 10:41			0